

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director

Governor GARY R. HERBERT

JON M. HUNTSMAN, JR.

Lieutenant Governor

Representatives Present During the Inspection:						
Company	Dennis Oakley Environmental Engineer					
OGM	Karl Houskeener, Environmental Scientist III					

Inspection Report

Permit Number:	C0150018		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, May 23, 2007		
Start Date/Time:	5/23/2007 9:00:00 AM		
End Date/Time:	5/23/2007 1:00:00 PM		
Last Inspection:	Tuesday, April 10, 2007		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Cloudy, Temp. 55 Deg. F. InspectionID Report Number: 1308

> Accepted by: pgrubaug 6/4/2007

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Current Ac	reages	Mineral Ownership	Types of Operations		
19,740.78 T o	otal Permitted	✓ Federal	✓ Underground		
97.74 T e	otal Disturbed	✓ State	☐ Surface		
	Phase I	\Box County	☐ Loadout		
	Phase II	✓ Fee	☐ Processing		
	Phase III	☐ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions: PacifiCorp will submit water quality data for the Deer Creek Mine in an electronic format through the EDI web site.

Inspector's Signature:

Date

Tuesday, May 29, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Wednesday, May 23, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.

 b. For PARTIAL inspections check only the elements evaluated.

 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		V	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		V	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0150018
Inspection Type: PARTIAL

Inspection Date: Wednesday, May 23, 2007

Page 3 of 3

2. Signs and Markers

The ID signs contained the necessary information. The signs are temporary signs until the new signs can be made and installed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond is being cleaned and the material is being hauled to the waste rock site.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2006 water monitoring is in the EDI website and has been uploaded. Water monitoring is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

Material from the sediment pond cleaning is being placed on top of the North side of the waste rock site. The pile appeared stable with no visible hazards.

18. Support Facilities, Utility Installations

The county has started construction work incident to the road upgrade in Rilda Canyon.